SMALL COIL REWINDS Pty. Ltd. 50 EDOLS STREET, NORTH GEELONG VIC. 3215 Ph. (03) 5278-8454

KLF300B/C Ignition Modules Part No. 21119-1241 / 1258 / 1302 / 1369 / TI-15

- **1.** Problems have been experienced with these units due in part to **OVER CHARGING** of the Battery. We believe that these Charging systems were designed to run ancillary equipment such as Boom-Sprays, Water Pumps, Electric shears etc..
- If accessory equipment is not used we **STRONGLY RECOMMEND** that one of the **ALTERNATOR PHASE WIRES** be disconnected, this being at the **STATOR TO MAIN HARNESS** connection which is located just under the **SEAT**. This should be taped out of the way for later use if required.
- **2.** Other problems such as **DETONATION**, **LACK OF POWER**, **MISFIRING**, **BACKFIRING** and sometimes they feel like they are **SEIZING UP**. These can be caused by the **PULSA** wires picking up **IMPULSES** from the **ALTERNATOR** wires which run together in the loom. This can be easily diagnosed by unplugging the **RECTIFIER/REGULATOR** unit.

If this fixes the problem, disconnect one of the *ALTERNATOR PHASE WIRES* at the connector and retest the unit, **ALL THREE WIRES MAY NEED TO BE DISCONNECTED TO FIND THE RIGHT ONE, BUT ONLY ONE CAN BE DISCONNECTED AT A TIME.**

- **3.** If **DETONATION** continues, the use of "**RESISTOR SPARK PLUGS**" and "**RESISTOR PLUG CAPS**" Will usually do the trick. <u>UNLEADED PETROL</u> is a must otherwise the Resistor Plugs will not last long.
- **4.** As the **RECTIFIER** / **REGULATOR** is located in a very **DIRTY spot**, it is very common for **CORROSION** to destroy the wire and connections. If the **BROWN** wire has no **CONNECTION** the output voltage will be **UNREGULATED**. Connectors are standard UTILUX parts.
- **5.** Due to **excessive heat** the WIRES on the alternator can become **very BRITTLE** and may cause a **SHORT** or **OPEN CIRCUIT**, when any replacements are made to the **CHARGE SYSTEM** all elements of the system **MUST** be thoroughly checked and **REPAIRED**.

*** NOTE: SOME IGNITERS ARE INTERCHANGEABLE BETWEEN MODELS.***

(B1 Only) 21119-1241, Marked with "WHITE number TI-15", will not interchange.

(B2 ->) 21119-1258; 21119-1302; 21119-1369; All will interchange.

The reason why they do not all interchange is because FLYWHEELS have different LENGTH "TRIGGER TIT". A's & B1 = 35mm, B2 -> = 25mm.

DISCONNECT ONE YELLOW (ONE PHASE) WHEN USING SH548-12 REGULATOR / RECTIFIERS.

IF MOUNTING WITH 2 BOLTS? LEAVE ONE LOOSE!!!